Montana Board of Oil and Gas Conservation Environmental Assessment

Operator: <u>Stealth Energy, USA Inc.</u>
Well Name/Number: Dejaegher 22-1

Location: NW SE Section 22 T11N R31E County: Rosebud , MT; Field (or Wildcat) W/C **Air Quality** (possible concerns) Long drilling time: No, 10 to 15 days drilling time. Unusually deep drilling (high horsepower rig): No, single or double derrick drilling rig to drill to 4,400' TD vertical Heath Formation. Possible H2S gas production: Slight. In/near Class I air quality area: No Class I air quality area. Air quality permit for flaring/venting (if productive): Yes, DEQ air quality permit required under 75-2-211. Mitigation: __ Air quality permit (AQB review) __ Gas plants/pipelines available for sour gas Special equipment/procedures requirements Other: Comments: No special concerns – using a single or double derrick drilling rig to drill to 4,400'TD Heath Formation test. **Water Quality** (possible concerns) Salt/oil based mud: No, freshwater, freshwater mud system. High water table: No high water table anticipated. Surface drainage leads to live water: No, closest drainage is the Musselshell River, about ¾ of a mile to the southwest from this location. Closest live water is the Delphia Melstone ditch, about 1/8 of a mile to the southwest from this location. Water well contamination: No, closest water well is about 5/8 of a mile to the southwest and ¾ of a mile to the south and southwest from this well. Depth of theses stock and domestic water wells are 25' to 137'. Surface hole will be drilled with freshwater and freshwater muds to 500' and steel 8 5/8" surface casing will be run and cemented to surface from 500' to protect ground water. Porous/permeable soils: No, sandy silty clay soils. Class I stream drainage: No, Class I stream drainage in the area. Mitigation: __ Lined reserve pit X Adequate surface casing _X Berms/dykes, re-routed drainage __ Closed mud system Off-site disposal of solids/liquids (in approved facility) Other: Comments: 500' of surface casing cemented to surface adequate to protect

Soils/Vegetation/Land Use

freshwater zones. Also, fresh water mud system to be used.

(possible concerns)
Steam crossings: None, only ephemeral drainages will be crossed.
High erosion potential: No, small cut, up to 3.7' and small fill, up to 4.9', required.
Loss of soil productivity: No, location will be restored after drilling, if nonproductive. If
productive unused portion of drillsite will be reclaimed.
Unusually large wellsite: No, a large wellsite of 200'X240' location size required.
Damage to improvements: No, slight, surface use is cultivated land.
Conflict with existing land use/values: Slight
Mitigation
Avoid improvements (topographic tolerance)
Exception location requested
X Stockpile topsoil
Stream Crossing Permit (other agency review)
X Reclaim unused part of wellsite if productive
Special construction methods to enhance reclamation
Other
Comments: Access will be from existing county road, Musselshell River Road and
existing two track well access road. Will build about 1043' of new access road. Drilling
fluids allowed to dry in the pits Drill cutting will be disposed of in the earthen reserve
pits, after being allowed to dry. Earthen pits will be backfilled when dry. No special
concerns.
Haakk Hawarda/Naiaa
Health Hazards/Noise
(possible concerns)
Proximity to public facilities/residences: Closest residences are about 5/8 of a mile to
the west and 7/8 of a mile to the southwest from this location.
Possibility of H2S: Slight
Size of rig/length of drilling time: Single or double derrick drilling rig/length of drilling
time, 10 to 15 days drilling time.
Mitigation:
_X_Proper BOP equipment
Topographic sound barriers
H2S contingency and/or evacuation plan
Special equipment/procedures requirements
Other:
Comments: Adequate surface casing and operational BOP equipment should
mitigate any problems.
Wildlife/recreation
(possible concerns)
Proximity to sensitive wildlife areas (DFWP identified): None identified.
Proximity to recreation sites: None identified.
Creation of new access to wildlife habitat: No
Conflict with game range/refuge management: None identified.
Threatened or endangered Species: Threatened or endangered species listed is the
Black-footed Ferret. Proposed listing is the Mountain Plover. Candidate specie is the
Greater Sage Grouse.
Mitigation:
Avoidance (topographic tolerance/exception)

Other agency review (DFWP, federal agencies, DSL)
Screening/fencing of pits, drillsite
Other: Comments: <u>Private surface lands. Utilizing existing roads and two track well</u>
access road for most of the access into this location. Surface is cultivated land. No
concerns.
Historical/Cultural/Paleontological
(possible concerns)
Proximity to known sites None identified
Mitigation
avoidance (topographic tolerance, location exception)other agency review (SHPO, DSL, federal agencies)
Other:
Comments: On private cultivated surface lands. No concerns.

Social/Economic
(possible concerns)
Substantial effect on tax base
Create demand for new governmental services
Population increase or relocation
Comments: No concerns.
Remarks or Special Concerns for this site
Well is a 4,400' TD vertical hole to the Heath Formation.
Summary: Evaluation of Impacts and Cumulative effects
No long term impacts expected. Some short term impacts will occur with the drilling of
this well.
I conclude that the approval of the subject Notice of Intent to Drill (does/does not)
constitute a major action of state government significantly affecting the quality of the
human environment, and (does/does not) require the preparation of an environmental
impact statement.
Prepared by (BOGC):_/s/Steven Sasaki
(title:) Chief Field Inspector
Date: September 1, 2010

Other Persons Contacted:
Montana Bureau of Mines and Geology, GWIC website
(Name and Agency)
Rosebud County water wells
(subject discussed)
_September 1, 2010
(date)
US Fish and Wildlife, Region 6 website
(Name and Agency)
ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES
MONTANA COUNTIES, Rosebud County
September 1, 2010
(date)
If location was inspected before permit approval:
Inspection date:
Inspector:
Others present during inspection: